

PART - I
PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/ Institution)

- 1 (a) Name of the school Khalsa College Public School Ghug
TEH. BHOGPUR, DISTT-JALANDHAR
- (b) Level/Standard of School:- 10+2
- © Whether School is affiliated to C.B.S.E. or P.S.E.B. If affiliated then affiliation No. C.B.S.E.
- 2 Location VILL- GHUG, TEH. BHOGPUR, DISTT-JALANDHAR
- 3 Plot Area 2.66 Acs (10,764 m²)
- 4 Plinth Area 457.5.25 m²
- 5 Number of Storey 3 (THREE) (G+2)
- 6 Year of construction of building 2024
- 7 If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given.
YES
- a) Name of the Engineer with Qualification ER. N.K. SHARMA MIE (CIVIL) FIV
- b) Address of the Engineer 30/1, Circular Road
AMRITSAR
- c) Detail of structural drawings used in the construction ATTACHED.
- d) Name & Address of Architect with qualification NIAMAN CONSTRUCTION, ARCHITECT
PARVEEN KUMAR, B.TECH. Reg. No: CA/98/23697
SCF 89, PHASE-7, MOHALI
- 8 Whether the building has been constructed for the purpose of
 - a) School SCHOOL
 - b) Residential purpose and converted for use as a school Only use as a school.
- 9 Material used for roofs
 - a) R.C.C. slabs RCC Slab
 - b) R.S. Joists & Battens N/A
 - c) Wooden Joists & Battens N/A
- 10 Material used for walls
 - a) Mud mortar N/A
 - b) Cement mortar Cement mortar
 - c) Plaster
 - i) Lime mortar Cement mortar
 - ii) Cement mortar
- 11 Flooring :-
 - a) Conglomerate Conglomerate (Tile Flooring.)
 - b) Terrazo
 - c) Brick paving
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. 20' x 26'5 (Drawing Attached)
- 13 Whether fire safety certificate obtained from concerned fire officer. A/F
- 14 It is also certified that there is no any court case or stay is pending regarding this building in any Hon'ble Court. No any Court case.

Principal
Khalsa College Public School
VII. Chug, Talwandi Bagra, (Jalandhar)

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE


(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)

Name of the School: Khalsa College Public School Ghug
Teh Bhagpur, Jalandhar

- 1) This office Assistant Engineer/Junior Engineer visited the above mentioned - School on 08-06-2024 and have visually inspected it for its safety and find it fit for normal use as a school building.
- 2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used) 2024-25 (up to 31-03-2025)

Ref. No. 30

Dated 14/6/2024


Sub Divisional Engineer,
Constn. Sub Div. No. 2
PWD B&R Br. Jalandhar Cantt

E-challan No. 12007815

Date - 18/6/24

Amount. - 10,000/-